

IMPORTANT SAFETY NOTICE

Recall to Repair Certain Bottom Freezer Refrigerators in Fingerprint Resistant Stainless Steel Sold Under GE Brand



Hazard: The freezer handle can detach when a consumer tries to open the freezer drawer, posing a fall hazard to the consumer.

Recalled Product: This recall involves six models of GE-brand French door refrigerators with bottom freezers in fingerprint resistant stainless steel, which were manufactured from February 2020 through August 2021. The brand name, model, and serial number for each unit are printed on a label located on the top of the left side of the interior of the refrigerator compartment.

Remedy: Consumers should contact GE Appliances, a Haier company, to determine if their unit is part of the recall, to schedule a free in-home service call to have their freezer's handle mounting fasteners replaced and their handle re-installed, and for instructions for safe use pending a repair.

www.geappliances.com/recall

or

Call toll-free at 888-345-4671

From 8 a.m. and 5 p.m. ET Monday through Friday

Recalled Models: Only refrigerators with one of the model numbers below and with a serial number that starts with one of the prefixes below are included in this recall. Consumers should locate the model and serial numbers on the product's rating label before contacting GE Appliances.

The affected models are: GFE26JYMKFFS, GFE26JYMNFFS, GNE27EYMKFFS, GNE27EYMNFFS, GNE27JYMKFFS, GNE27JYMNFFS

The serial numbers for the affected models begin with one of the following two letter combinations: DR, FR, GR, HR, LR, MR, RR, SR, TR, VR, ZR, AS, DS, FS, GS, HS, LS, MS.